



Dave Romesburg &lt;dromesburg@gmail.com&gt;

---

## # 27 Castle View Drive (November 28th 2005)

1 message

---

**Dave J Romesburg <dromesburg@gmail.com>****Mon, Nov 28, 2005 at 7:17 PM**

To: kgz@heartlandonline.com

Craig

please call me and confirm you received these pictures.. Please note the following;

really hasn't rained however it was 68 degrees today, so what was frozen is now wet.

1. look at the pictures of our garage wall, first 3 pictures and DSCN0184.JPG

2. DSCN0179 - new water spot coming in around media box, the board behind the media box was already replaced once.

3. DSCN0181.JPG and DSCN0182.JPG - i moved the boards up against our long basement wall on the side of our house just out of curiosity since our basement is loaded with stuff.. Take a look, water coming in there also.

4. NOTE all of the pictures from outside - our house is now loaded with chaulking instead of fixing whatever the problem is, HHI or whomever looked at this now loaded our house up with layers upon layers of chaulking. This is unexceptable and I will not try to sell our house at any time with 2 - 3 layers of chaulking ALL around our front stoop. Unacceptable, totally unacceptable. Look at our dryer vent, do you think they could have loaded MORE chaulking around the vent itself?

Supposedly you fix a few areas, then new areas pop-up and this is really getting old.. Do whatever you need to do in January I've contracted with Hyatt Legal services through my employer and they will handle anything consumer protection related. This is no further ahead than it was before and I really can't believe this...

I really think I've been MORE than patient and now I am just totally upset now that I finally get a chance to look at the outside of our \$200,000.00 house to find chaulking loaded everywhere in layers and layers...

I just can't believe HHI builds or contracts out to build houses! There are no words to describe this, none at all!

Dave Romesburg  
cell - 412-977-9965

You have been sent 32 pictures.

DSCN0166.JPG

DSCN0167.JPG  
DSCN0168.JPG  
DSCN0169.JPG  
DSCN0170.JPG  
DSCN0172.JPG  
DSCN0173.JPG  
DSCN0174.JPG  
DSCN0175.JPG  
DSCN0176.JPG  
DSCN0177.JPG  
DSCN0178.JPG  
DSCN0179.JPG  
DSCN0180.JPG  
DSCN0181.JPG  
DSCN0182.JPG  
DSCN0184.JPG  
DSCN0185.JPG  
DSCN0186.JPG  
DSCN0187.JPG  
DSCN0188.JPG  
DSCN0190.JPG  
DSCN0192.JPG  
DSCN0193.JPG  
DSCN0194.JPG  
DSCN0196.JPG  
DSCN0197.JPG  
DSCN0198.JPG  
DSCN0199.JPG  
DSCN0200.JPG  
DSCN0201.JPG  
DSCN0202.JPG

---

**32 attachments**



**DSCN0166.JPG**  
33K



**DSCN0167.JPG**  
41K



**DSCN0168.JPG**  
34K



**DSCN0169.JPG**  
33K



**DSCN0170.JPG**  
36K



**DSCN0172.JPG**  
33K

**DSCN0173.JPG**  
35K



**DSCN0174.JPG**  
30K



**DSCN0175.JPG**  
33K



**DSCN0176.JPG**  
32K

**DSCN0177.JPG**  
30K



**DSCN0178.JPG**  
32K



**DSCN0179.JPG**  
34K



**DSCN0180.JPG**  
41K

**DSCN0181.JPG**  
35K



**DSCN0182.JPG**  
40K



**DSCN0184.JPG**  
28K





**DSCN0185.JPG**  
28K


**DSCN0186.JPG**  
34K





**DSCN0187.JPG**  
35K


 **DSCN0188.JPG**  
43K


 **DSCN0190.JPG**  
31K


 **DSCN0192.JPG**  
35K


 **DSCN0193.JPG**  
36K


 **DSCN0194.JPG**  
36K


 **DSCN0196.JPG**  
45K


 **DSCN0197.JPG**  
40K

 **DSCN0198.JPG**  
42K

 **DSCN0199.JPG**  
34K

 **DSCN0200.JPG**  
25K

 **DSCN0201.JPG**  
25K

 **DSCN0202.JPG**  
33K

---